

the condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is con-
sidered due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next
periodical examination, a distinguishing mark thus ∇ should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs".

Loss is subject to main circulating pump casing
examined next DD, and to first length disc.
from main circulating pump being renewed or repaired 5 E
Ext 55.

Engineer Surveyor.

Received from Chief Engineer Surveyor.

STANVAC SYDNEY REPORT KORE No. 4196

Works of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
presented in the endorsement. (Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE & WEAR AND TEAR.

due 7.56, now held
due 9.56, now held
due 10.57, now held
due 7.58, now held

Above items now efficiently dealt with & may be
deleted.

is submitted the vessel is eligible to remain as classed, with

Record of Survey ES 11.56
MBS 11.56
SPS 11.56
TSCL 10.56 } as recommended, without special
condition

3.5.57

JC.

© 2020



Lloyd's Register
Foundation

003631-003639-011

Date of Committee

ES 11.56 without Spl Condn