



NOTES

- EXIST VENTS TO BOAT DECK TO BE EXTENDED THROUGH QUARTERS AND MODIFIED AS SHOWN.
- PORT BOLTED PLATES ARE TO BE 14\"/>
- FIELD END OF BOILER IS TO BE EXTENDED UP & OUT TO FOR AFT. END CREWS QUARTERS.
- ALL WORK TO BE IDENTIFIED FROM SHIP.

TAMPA SHIPBUILDING CO. INC.
TAMPA, FLA.
MARINE REPAIRS, STEVEDORE DIVISION

DWG. NO. 6-593-C40

DRAWN BY RS
SCALE - SHOWN

M/S ONDINA
Jck. Tpr. #1224

GUN CREW'S QUARTERS
FORD END OF POOP DECK