



# Lloyd's Register of Shipping,

Prins Hendrikkade 86,

Amsterdam, 15th June, 1936.

The Secretary,

LONDON.-

AMSTERDAM DISTRICT.

All communications to be addressed to—  
THE SURVEYORS.

Reference

S.

LLOYD'S REGISTER  
RECEIVED  
16 JUN 1936  
AMSD.  
LONDON

Dear Sir,

With reference to your letter of the 12th instant respecting the motor vessel "MACOMA", Report No. 13698, I beg to confirm that the size of the power driven lubricating oil pumps are the same as for the sister ship "ROTULA".

I beg to state that each air receiver is fitted with a safety valve, the internal surfaces of these receivers can be examined and cleaned (manholes) and the drain is fitted at the lowest part of each receiver.

I am sorry that these items were omitted on my report.

I am, Dear Sir,

Yours faithfully,

*B. J. J. J.*



© 2020

Lloyd's Register  
Foundation



RECEIVED

MADEIRA, 18th Dec 1930

1033

Memorandum to the Chief Engineer Surveyor

at the Admiralty

Subject: ...

...

...



© 2020 Lloyd's Register Foundation

Referred to the Chief Engineer Surveyor

Handwritten signature

also for Mr. Spinks to note.

16 JUN 1930

...

...

...

Rules be cl

...

Frame

2nd I

1st I

The rem

SEL'S

red by

Total

and Uppe