

Received from Chief Ship Surveyor 20 JUL 1959

SHIP'S NAME "MACOMA" REPORT Dja. No. 5619

GB

Outstanding Conditions of Class: SUBJECT to indented shell plates
G.10 & H.10 (s.s.f) and wasted shell plates A.2 & 3 (p.s.f)
(locally doubled 9,58) being specially examined and dealt
with as necessary by the Special Survey.

Endorsement of Certificate (As before ~~on None~~)

Surveys due: SPECIAL SURVEY (C) due 5,59. Postponement of Special
Survey until 10,59 approved-(see letter 6.5.59.)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Examination and repair of defective steering gear.

Special Features:

Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

S. to be completed by: 10,59.

Recommendation:

SUBJECT as above, but further ACTION
be DEFERRED for Special Survey.

SUBJECT

IN S.R.L. APPENDIX

Shell plate G.3 (s.s.a) indented.



© 2020

Lloyd's Register
Foundation

17/7/59