

Monrovia, whilst afloat at Amsterdam on the 6th Sep-

The class is subject to the cement round sea valve chests moved, and chests being specially examined and dealt with as necessary at the Special Survey, also to the starboard forward armature being replaced and examined under working conditions

Received from Chief Engineer Surveyor

4E

11 OCT 1957

"ELENE".

REPORT

AMS.

No. 21690.

by 10.57.

DBS due 5.57, partly held 7.57, not advanced.

C.S. Advanced.

The starboard forward generator armature now replaced and repaired, and the generator tested under working conditions and satisfactory. To be deleted from the SRL.

IT IS SUBMITTED that this vessel is eligible to remain in class, subject to the cement round sea valve chest being removed and dealt with as necessary at the Special Survey, without other special condition.

9.10.57.

Lloyd's Register
Foundation

003649.003658-0225