

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report \_\_\_\_\_ 19\_\_\_\_ When handed in at Local Office \_\_\_\_\_ 19\_\_\_\_ Port of London

No. in Reg. Book. 13703 Survey held at on the Wood, Iron or Steel Date, First Survey Sc. K. "P. Cannon" Last Survey 19

TONNAGE:— Built at Aberdeen By whom A. Hall & Co. When 1915 7  
GROSS 211 Owners Abn. Pioneer Sp. Fishing Owners' Address \_\_\_\_\_  
UNDER DK. 207 Managers H. Stroud & Co. Port belonging to Aberdeen  
NET 78

Surveyed Afloat or in Dry Dock? \_\_\_\_\_ Name of Dock \_\_\_\_\_ Destined Voyage \_\_\_\_\_

WB=CellDBorDBa \_\_\_\_\_ feet; uE&B \_\_\_\_\_ feet; f \_\_\_\_\_ feet }  
total capacity \_\_\_\_\_ tons. FPT \_\_\_\_\_ tons; APT \_\_\_\_\_ tons; MT \_\_\_\_\_ tons. }  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100 A</u>		<u>+ Feb 4.28</u>
<u>Steam Trawler</u>		<u>BD 7.32</u>
<u>4/31</u>		<u>of 3/31</u>
<u>Abn No 3/4/28</u>		<u>(N) 5.33</u>

Report, No. 17334 Port Abn

Special Surveys, when held, must be reported in detail and serialism in the terms of the Rules. State clearly the nature of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he has declined his services for this purpose and to whom and why they were declined \_\_\_\_\_

Society's Freeboard (if assigned) as \_\_\_\_\_ ft. \_\_\_\_\_ ins.  
painted on Ship and now verified \_\_\_\_\_

Was a damage report made by anyone else? If so, by whom? \_\_\_\_\_

REPAIRS, OR EXAMINATION AS PER RULE, FOR \_\_\_\_\_

**WRECK SECTION**  
No. 729

STATEMENT OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

### PRESENT CONDITION OF THE

Condition of Decks	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Platings	State if Tanks now tested	Engine Room Skylights	(State if on Feet). When put on, Month _____ Year _____
Rivets & Fastenings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Bottom Plating	Ceiling	Scuppers	Masts, Yards, &c.
Stanchions	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained
Stays	Rudder	Hatches	(State if wedges removed)
Stem	Steering gear and its connections	Planking of Wood Vessels	Sails
Stem Frames	Windlass	Caulking ditto	Equipment letter
Stemsonals	Have Pumps now been examined and found efficient?	Treenails ditto	Anchors, No. of _____
Stems	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
Stems	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length _____ size _____ (on board)
Stems	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length _____ size _____
Stems		Ditto Ditto at other places ditto	Hawser & Warps
Stems		Stringers, Clamps & Shelves ditto	Standing and Running Rigging
Stems		Salting (State if examined.) ditto	

### General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

10ms. 1933. Transfer Ink not to write on or below the space

Survey Fee (per Section 29)	Special Damage or Repair Fee (if any) (per Sec. 29)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for,	Received by me.
£ _____	£ _____	£ _____	£ _____	19 _____	19 _____

**WRECK SECTION**  
No. 729

Committee's Minute **REL 1 SEP 1933**  
Expense classed with any 20.2.9.33  
abn Lloyd's 1933

Surveyor to Lloyd's Register of Shipping.  
General Committee  
Thursday, 7th September, 1933.  
Decision of Classing Committee confirmed

5600-879500-179500

Is Certificate required? If so, to be sent to \_\_\_\_\_