

29 FEB 1944

23850

Index No.

Rpt. C. 11 (Contd.)

# Lloyd's Register of Shipping.


Ship's Name "RADMANSO"

Official No. 5642.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

Hatch covers in shelter 'tween decks found deficient and permit for new covers refused.

As a temporary measure the access openings in the forward bulkhead of the tonnage well have been plated over (bolted and nuts welded on) and securing plates have been welded over the existing screw plugs in the overboard scuppers. Two scuppers have been fitted each side to the machinery space bilges and there is clear drainage to these from all parts of the 'tween decks.



SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.

*Noted*  
29 FEB 1944  
A.P.S.

*note! In reply to an enquiry of the outdoor Surveyors London the closing appliance of the forward tonnage well which were examined 12.7.45 and reported to be steel clowd with bolted steel plates & no further repairs or renewals appear to have been made to the tween deck hatch covers per the Jenkins. 12.7.45.*

