

BALANCED REACTION RUDDER COMPANY LIMITED.

DIRECTORS:

SIR JOHN PRIESTMAN, BART.
EDMUND C. THOMPSON,
JOHN TUTIN, D. Sc.

TELEPHONE: MANSION HOUSE 4013.

CODE: A. B. C. 5TH ED.

26, FENCHURCH STREET,

LONDON, E. C. 3.

9th November 1935.



URGENT.

The Secretary,
Lloyd's Register of Shipping,
LONDON E.C.3.

Dear Sir,

S.T. "WHITE PIONEER".
(J. LEWIS & SONS NO. 134.)

It is desired to add a plate 6 inches in width and .80 inches thick to the after edge of this rudder, extending for the full height of the rudder, and if possible, it is hoped to make this small extension in the course of the next few days.

As the upper stock and mainpiece and pintles were kept in excess of your minimum requirements, it is hoped that you will sanction this extension.

Yours faithfully,

FOR
BALANCED REACTION RUDDER Co., Ltd

MANAGING DIRECTOR



© 2020

Lloyd's Register
Foundation

003750-003762-0045

Referred to the Chief Ship Surveyor.

MP

-9 NOV 1935

URGENT.

London Telegraph.

Yours very truly,
Chief Ship Surveyor.

As the vessel is under charter to the Government, it is hoped that
the Government will be able to arrange for the vessel to be
kept in service at all times, and that the vessel will be
able to return to the service as soon as possible. It is hoped that
the vessel will be able to return to the service as soon as possible.
The vessel is under charter to the Government, and it is hoped that
the Government will be able to arrange for the vessel to be
kept in service at all times, and that the vessel will be
able to return to the service as soon as possible. It is hoped that
the vessel will be able to return to the service as soon as possible.



© 2020

Lloyd's Register
Foundation

RECEIVED
LONDON
11-10-35

RECEIVED
LONDON
11-10-35

RECEIVED
LONDON
11-10-35

RECEIVED
LONDON
11-10-35

RECEIVED
LONDON
11-10-35

RECEIVED
LONDON
11-10-35