



# Lloyd's Register of Shipping,

95, Bothwell Street, GLASGOW, C.2.

7th August, 1944.

RECEIVED

28 AUG 1944

Dear Sir,

E.

Messrs. Fairfield S.B. & E. Co., Ltd., No. S.O.6915.  
Screw Shafts for M.V. "CHESHIRE" (No.71953 in R.B.)  
Built in 1927.

I beg to acknowledge receipt of your letter of  
the 4th instant and wire reading as follows:-

"CHESHIRE YOUR LETTER FIRST INSTANT PROPOSED METHOD OF REPAIR  
PORT SHAFT CAN BE ACCEPTED PROVIDED SURVEYORS ENTIRELY  
SATISFIED STOP LINER OF STARBOARD SHAFT SHOULD BE CUT BACK AS  
INDICATED IN PENCIL ON PLAN AND SURVEYORS SHOULD SATISFY  
THEMSELVES BY MEANS MAGNETIC CRACK DETECTOR OR SIMILAR MEANS  
THAT DEFECT DOES NOT EXTEND BELOW BOTTOM OF GROOVE."

I am, Dear Sir,  
Yours faithfully,

*Thurley*  
Local Secretary.

The Secretary,  
71, Fenchurch Street,  
LONDON.



Lloyd's Register  
Foundation

003769-003777-0037



Referred to the Chief Engineer Surveyor

17-8 AUG 1944

HB



© 2020

Lloyd's Register  
Foundation