

Steering Chains (Size and Test)

None.

Windlass

Steam & Diesel by J. H. Hemmell & Son Ltd.

Boats

Req. 1 (Tr.).

(Received at London Office,.....)

No. 3259

Port

HULL

Date

3rd JAN.

1941

We

request that the

SINGLE

SCREW

Steam Trawler Building

for

BRITISH ADMIRALTY

by

COOK, WELTON & GEMMELL LTD

of

520

Tons.

Length,

165'

B.P. breadth,

28'-0"

MLD depth,

15'-0" MLD.

may be Specially Surveyed while building (100 AI STEAM TRAWLER)

If for a particular term or class, state the same.

We hereby engage to pay the established Special Survey Fees in accordance with the Society's Rules for Trawlers as follows, also the fees for inspection of installation of Electrical Fittings as set forth in the Society's Rules for Electrical Equipment.

For trawlers built under the special superintendence of the Surveyors (to entitle them to the distinctive mark †), 2s. per ton gross. No fee to be less than £10.

For engines and boilers built under the special superintendence of the Surveyors (to entitle them to the distinctive mark † in red): — Five shillings per Nominal Horse Power. No fee to be less than £9.

The Nominal Horse Power for regulating survey fees on engines and boilers to be determined as described in Section 29. Entry Fees as per Section 28 are additional to the above charges.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling expenses are incurred by the Surveyors in connexion with the above services, they are to be defrayed by the parties interested.

In no case can the vessel be classed until all fees, travelling expenses, &c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

No. 683 in Builder's Yard.

Manufacturers of Engines

C. D. HOLMES & Co. Ltd. Hull

Ditto of Boilers

ditto.

To the Secretary,

Signature

COOK, WELTON & GEMMELL LTD.

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

CHIEF DRAUGHTSMAN

605769 003777 -0107

Lloyd's Register Foundation