

4 NOV 1957

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

P'S NAME

"LILIAN"

REPORT

Vpo.

No. 3916

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

The class of this ship was expunged from the Register Book for non-compliance with the Society's Rules 7,57. See Committee Minute 26.11.57.

A SPECIAL SURVEY (C) became due 2,57.

The VALPARAISO Surveyor reports (9,57), this ship examined afloat and in dry dock and the major part of a Reclassification Special Survey held.

The Surveyor further reports it is the Owners' intention to complete the Special Survey in about one months' time.

On account of wear and tear repairs effected to shell plating and internals etc.

On account of damages (causes unknown) shell repairs deferred until Owners' convenience.

The Surveyor also reports the Echo Sounding Device has now been removed.

FOR ITEMS TO COMPLETE THE S.S.:- See this report.

See letter from Valaparsio Surveyor dated 19.10.57 regarding Owners' financial status.

IT IS SUBMITTED record of 'DS 9,57' and Notation of 'SS Vpo. 9,57' be WITHHELD pending completion of the Reclassification Survey.

DELETE FROM R.B.
ESD.

ENDORSEMENT OF CERTIFICATE.
Indented shell plates (p & s).

RECLASS.SURVEY
PART HELD.

IT IS FURTHER SUBMITTED the VALPARAISO Surveyor's attention be drawn to the Rule requirements contained in Chapter B, Section 15, Para.1501 re Reclassification of Ships.

X 13/12



© 2021

31.10.57.

Lloyd's Register
Foundation

003778-003787-0081