

Received from Chief Ship Surveyor.....

10 DEC 1958

SHIP'S NAME "ONORATO"

REPORT Gen.

No. 23755

GB

Outstanding Conditions of Class:

Subject to sternframe 'E.W. & reinforced 7,56) being specially examined at next drydocking.

Endorsement of Certificate (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

Docking: Repairs (wear and tear):
Examination of deferred items as above.

Recommendation:

SUBMITTED record of 'DS 11,58' be assigned,
but without special condition.

DS 11,58 Without.

S.R.L. APPENDIX NOTE (AMENDED).

No.2 keel plate and B.1 (s.s.) slightly indented.
Slight buckling of B.R. forward bulkhead (p.s.).
Shell plates D.3, 4, 5 & 8 (s.s. from fwd) indented.

IT IS FURTHER SUBMITTED the Genoa Surveyors be advised
that due to the satisfactory condition of the sternframe
(E.W. & reinforced 7,56) this condition of class has been deleted.

Blk (new)

1.55, and the notation of S.S. . . . 1.55".

This ship so far

003788-003799-0030

2020
Lloyd's Register
Foundation
06/1/12/58