

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

28th May, 1963

C
NS/RW

Dear Sirs,

M.V. "WAIRANGI"
Refrigerated Cargo Installation


A Report has been received from the Society's Buenos Aires Surveyors in respect of a survey carried out between the 15th and 16th April last.

At this time, leakage of oil fuel was reported in the starboard bilge of No. 3 lower hold, and it was recommended that Nos. 4 and 5 D.B. tanks be kept empty until after discharge of cargo and until arrival U.K. port by the end of June, 1963, when, it is understood, repairs will be carried out.

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Shaw, Savill & Albion Co. Ltd., © 2020
Cunard House,
88, Leadenhall Street,
LONDON E.C.3



Lloyd's Register
Foundation

003816-003823-0113

003816-003823-0115 1/2