

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME

Paul P. VENCROFT

Report

Gls

No.

49642

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

ure of Survey

1st Entry

When due

Revised Rules


+ 100 A.1 (Pile)

1 D² (Pile) Well D².

Cell DB f 116' 1835 FPT 785 APT 555.

FK BBH Asp Lloyd's A & C.P.

Q 110' , B 11' , F 28' Machy aft.



© 2020

Lloyd's Register
Foundation

003816-003823-0195