



# LLOYD'S REGISTER OF SHIPPING

REGISTERED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street,

97/56

London, 10th December, 1956.

E.C.3

To the Surveyor at HONG KONG

## LOCATIONS

Name m.s. "SRI TINJAR" Tons Gross 257 No. in Reg. Bk. 78581

### QUESTION.

According to information received in this office, this ship was adrift on 12th November while being towed to Hong Kong for survey. Nothing further has been reported, please enquire and state whether she has arrived at Hong Kong.

*Jda*

### ANSWER.

Date:— 17th December, 1956.

There has been no news of this vessel since she broke adrift while under tow to Hong Kong and it is generally assumed that she is lost.

*pac*

This form is to be returned to the Secretary as soon as the information asked for has been filled in

003824-003831-0026

© 2020

Lloyd's Register  
Foundation