

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C.3

Classn(S)

21st October, 1953.

CFA

Dear Sirs,

Motorships "SRI TUTOH"
"SRI TINJAR"

With reference to your letter of the 7th instant and enclosed copies of reports received from Lloyd's Agents at Labuan, North Borneo, I shall be glad if you will ascertain and let me know whether the anchors and cables forwarded from Hong Kong have been placed on board these vessels.

In this event, you should arrange for the equipment to be verified with the under-mentioned certificate numbers, and for the necessary reports to be forwarded:-

	<u>"SRI TUTOH"</u>	<u>"SRI TINJAR"</u>
Bower Anchors	Y7413 and Y7414	Y7411 and Y7412
Stream Anchor	Y4718	Y4717
Stud Link Chain	Y4734	Y4733
Cable	Y4737	
Stream Chain		Y4736

The assignment of class in each case is being withheld meantime.

Yours faithfully,

Assistant Clerk to the
Classification Committee.

The Surveyors,
SINGAPORE.



© 2020

Lloyd's Register
Foundation

003824-003831-0045