

COPY

Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)

2318



This Certificate
Accompanies

REPORT No. 2318
Dated 15-7-57

Port

YOKOHAMA

15th July, 1957

This is to Certify that I have

Surveyed the ^{Part} Boiler and Machinery of the M/V "ROTULA" 8060 tons
gross of The Hague, whilst she lay in dry dock and afloat at Yokohama,
on the 26th June 1957 and subsequently

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of TS 6,57 CL., DBS 6,57 (now)
and Continuous Survey of Engines (CS) with date

be made in the Register Book in the case of this vessel when

the survey has been completed, subject to the Port and Stbd. fwd. pumproom
sea valves being renewed in steel by 6,58 (12 mos limit).

Parts now examined:— Propeller, Screw shaft and external fastenings.

Nos. 2 & 3 Cylinder liners, Covers, Pistons, and Rods, Valves and Valve gear.
Nos. 2 & 7 Con-rods, Top Ends and Guides.
Nos. 4 & 5 Crankpins and Bearings.
Nos. 1 & 2 Journals and Bearings.

Aux. Condenser, Forward Feed Pump, O.P. Transfer Pump, Butterworth Pump,
F.W. Cooler, H.V.O.P. Heater, Butterworth Heater, Main Starting Air Receiver,
Aux. Diesel Engine.

Donker Boiler and Mountings etc. and safety valves adjusted under steam
at 180 lbs/in².

Compression Ring Sizes:— Fwd. 11.35mm Aft 2.25mm

W. Armstrong

Engineer Surveyor to Lloyd's Register.

W. ARMSTRONG.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are
properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any
circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its
Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or
negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

CRET. BL. (C.S.) 156. KOB

003824. 003831-0184