

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl Se "MAHOUT"Report Snk No. 18466**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

Nature of Survey 1st Entry

When due _____

Revised Rules _____



✱ 100 A.I. (Steel)

2 dks (Stl), 3rd dk (Stl) in No 1 hold.

Cell D.B. 395' 1502t, D.T. a 36' 1228t, F.P.T. 76t, A.P.T. 93t.

F.K, 8 B.H. (1 B.H to 2nd dk), pt Cen, Lloyds A.C.P.

PH6, B 158, F 39'.

003832-003837-0008

Foundation Plate on }
Floors }

No Hold Only.

Third Deck, amidships, Angle F or F



© 2020

23.12.25

Lloyd's Register
Foundation