

6m,9,61

4E

Class is subject to the propeller being specially examined and dealt with as necessary at the next dry docking.

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... 17 NOV 1961

SHIP'S NAME..... "MAI RICKMERS"..... REPORT..... HAM..... No. 10958.

MBS due 5.61. Partly held 5.61. Now completed.

SRL.

The condition of the propeller is reported as being good and in the circumstances it is submitted that this item be deleted from the Special Reasons List.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of MBS 8.61 without special condition.

47



© 2020

16.11.61.

Lloyd's Register Foundation

003832-003837-0052