

5 E

d by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

"S NAME "DONGOLA" REPORT Bom No. 11187

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey


~~DAMAGE & WEAR AND TEAR.~~

Vessel examined in drydock and the sea connections opened up and examined.

It is submitted the vessel is eligible to remain as classed, with ~~with~~ as recommended.

~~Record of Survey~~

Note for RMC:- Sea inlet and discharge valves examined 11,54.



© 2020

Lloyd's Register Foundation

30.12.54

003832-003837-0190