

SUNETTA

(Tanker built <sup>1935</sup>1930)

The drillings forwarded with Singapore Report No. 13687 have been examined for diminution of upper deck and shell plating. The next due date for drilling is 10-65, but the present drilling was carried out at the request of the Owners.

IT IS SUBMITTED the Shell Petroleum Co. be informed that an examination of the upper deck and shell plating over the cargo tank length, as shown on Singapore Harbort Board's Drawing No. R/1431, indicates that renewals will be necessary at the Special Survey in 10-61 and that these have been indicated in red on the above drawing for their guidance, it being assumed that the drillings are representative of the general condition of the plating. Recommendations for renewal of plating outside the cargo tank length, and any amendments to the renewals indicated at present, that may be necessary, will be made by the Society's Surveyors at the time of survey.

Copy of letter to Singapore Surveyors who should be requested to send an additional copy of the plan for eventual transmission to the surveyors when the special survey is carried out.

*Old*  
4th March, 1960 *John*

*JW*



© 2021

Lloyd's Register  
Foundation

005838-005845-0028