

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME "SUNETTA" Rpt. Rot No. 23510a

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

It is submitted the Rotterdam Surveyors be requested to forward by return a complete Rpt. 1* with the scantlings of the transverses in the bottom and the deep plate side stringers inserted.

The copy of Rpt. 1* should be returned.

The Surveyors should be informed that it would be advantageous if copies of midship section and profile and decks as built could be forwarded to this Office.

Mr 4/3/75



© 2021

11.3.35
Lloyd's Register
Foundation

003838-003845-0048