

# RINGSEND DOCKYARD (DUBLIN) LTD.



SHIP BUILDERS, SHIP REPAIRERS  
MARINE & GENERAL ENGINEERS  
AND  
STEELWORK CONTRACTORS

GRAMS:  
RINGSEND DOCKYARD

PHONES:  
DUBLIN 61060  
35480 (AFTER OFFICE HOURS)

PRIVATE GRAVING DOCKS 148 FEET LONG AND 90 FEET LONG SITUATED IN WORKS  
PUBLIC GRAVING DOCK 412 FEET LONG  
PUBLIC SLIPWAY 180 FEET LONG

DIRECTORS:  
G. BROCK, F.C.A.  
MRS. J. C. McMILLAN

GENERAL MANAGER:  
W. E. ALEXANDER

OURS **WEA. EP**  
REF  
YOURS

GRAND CANAL BASIN  
RINGSEND

DUBLIN, S.E. 25th June 1942

R. B. Grier Esq.,  
Lloyd's Surveyor,  
Lloyd's Register of Shipping,  
30a. Lr. O'Connell Street,  
DUBLIN.

Dear Sir,

## M. V. "GOLDFINDER"

### Re Installation of "Allen" engine.

We submit for approval Prints in triplicate, showing proposed arrangement of seating to accommodate in above vessel new engine ordered by Owner, Mr. H. Wilson, Wexford, from Messrs. W. H. Allen & Sons, Bedford, in substitution for damaged 8 cylinder 250 B.H.P. 350 Rev. Benz engine originally installed.

The new engine is described by Messrs. Allen as 6 P.S.30 B oil engine and R/R gear box 6 cylinders 230 m.m. bore x 300 m.m. stroke 250 B.H.P. at 600 RPM. Propeller shaft speed 270 R.P.M.

It is proposed to fit two longitudinal girders on top of existing welded seating. Girders to be formed of rolled steel channels 12" x 3½" x 3½" x 29.23 lbs per foot (Makers, Messrs. Dorman Long, Middlesbrough) reinforced on upper flange with 4" x 5/8" m.s. flat and web stiffened by 5/8" bracket plates fitted at each floor for extent of engine bedplate.

The girders would be attached to existing engine seat bedplate by continuous fillet electric welding and would be fabricated in same manner.

The Owner is anxious that this work should commence with least possible delay and we trust, in these circumstances, you can obtain telegraphic approval from London.

Yours faithfully,

Encs.

RINGSEND DOCKYARD (DUBLIN) LTD.

*W. E. Alexander*

GENERAL MANAGER

005838-005845-0140

© 2021

Lloyd's Register  
Foundation