

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

L'S NAME Steel Tw. Sc. M.S. "TRICOLOR" Rpt. Ams No. 12937

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92*).

of Survey _____

It is submitted before this case receives the consideration of the Committee the Surveyors should be requested to state whether they are correct in reporting the riveting of the butts of the shell bottom, bilge plating and the strake below the sheerstrake as being treble riveted, and whether the increased thickness of shell plating shown on the report at the fore end of vessel extending 2'-0" below the ^{BALLAST.} ~~light~~ line and 2'-0" above the load line meets the Owners' requirements.

Ans
9/6/33

The Surveyors should also be requested to forward a copy of the midship section of vessel as built



© 2021

Lloyd's Register
Foundation

[Handwritten signatures and initials]

003838-003845-0170