

SHIP NAME "ATHOS"

REPORT Piraeus

No. 6737

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in hundredths of an inch.

PLATE.	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness	Thickness by drilling.		Diminution if any.		Original Thickness	Thickness by drilling.		Diminution if any.		Original Thickness	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
side.	53	45	45	08	08	40	34	34	06	06	36	36	36	-	-	A number of odd shell plates renewed or doubled as considered necessary.
ke below	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
RAKE	58	56	56	02	02	42	34	34	08	08	42	40	40	02	02	
elow	58	56	56	02	02	42	36	36	06	06	42	42	42	-	-	
G	58	56	58	02	-	42	36	36	06	06	42	40	36	02	06	
F	58	58	56	-	02	42	50	36	-	06	42	40	40	02	02	See body of Report.
CE	59	56	58	03	01	44	38	42	06	02	44	38	38	06	06	
D	59)					44)					44)					
C	59)					44)					44)					
B	59) Cement.					44) Cement.					44) Cement.					
A	59)					44)					44)					Upper Deck plating now good.
al	70)					63)					63					

Drillings at ends to be made in the vicinity of the peak bulkheads.

003838-003845-0215