

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

12th July, 1949.

Dear Mr. Westbury,

T.S.S. "LUCIA"

S.

The Committee have had before them your reports of survey Nos. 3251a & 3251b held on this vessel in April last on account of damage stated to have been sustained when a hole was burned through the stringer plate in way of No. 3 starboard cargo tank and extensive renewals and or repairs were effected to shell, deck, bulkheads etc. in way of No. 3 starboard wing tank.

I am sorry to trouble you while on leave, but we are desirous of knowing the cause of the damage which necessitated these extensive repairs, and if you are in a position to do so without recourse to your records in Curacao, I shall be glad to receive your views.

With kind regards,
Yours sincerely,

C.H. Westbury, Esq.,
23, Norwood Avenue,
LIVERPOOL 21.



© 2021

Lloyd's Register
Foundation

003838-003845-0247