

COPY

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

Enclosure

30th September, 1947.

3. Dear Sir,

S.S. "YEWFOREST"


I duly received your letter of the 26th ultimo regarding Greenock Report No.23534 and have to say that Dr. Webster's view in regard to this vessel's equipment is concurred in.

The class assigned therefore is subject to 15 fathoms of chain cable being supplied and the conditions of class of the Steamers "THE EMPEROR" and "THE MONARCH" have been similarly amended.

I forward herewith the Classification certificate for the "YEWFOREST" and have to request that when transmitting this to the Owners you will draw attention to the fact that the bottom in way of the machinery space will require to be examined internally annually owing to the omission of the cement.

I shall also be obliged if you will request the Greenock Surveyors to confirm whether the safety valves are of the 'high lift' or 'improved high lift' type.

Yours faithfully,

 Lloyd's Register of Shipping
Clerk to the
Classification Committee.

The Secretary,

to accord with the requirements of the Rules when the vessel is in the present state of emergency has a...

003846-003857-0026
158800-0026
7