



Lloyd's Register of Shipping,

RECEIVED 95, Bothwell Street, GLASGOW, C.2.

27 AUG 1947

26th August, 1947.

Dear Sir,

ANSD.....

With reference to Greenock Report No. 23534 on the Steamer "YEWFOREST", which received the consideration of the Glasgow Sub-Committee of Classification at their Meeting to-day, Dr. Webster has asked me to point out it is considered here that 15 fathoms of 1.7/16" cable is all that is required to bring the cable to Rule standard, it being observed that the Rules require cable of 1.6/16" diameter for a vessel of this type and size. I shall, however, be glad to receive your instructions in the matter and would refer you to the cases of "THE MONARCH" and "THE EMPEROR", similar vessels, which were recently classed with this Society.

I am, Dear Sir,

Yours faithfully,

The Secretary,
LONDON.



© 2020
Secretary to the
Glasgow Committee

Lloyd's Register
Foundation

002846-003857-0028

Referred to Mr. Pento

RJ
for S. to make

SpL

Submit for approval.
the conditions regarding
the modified accordingly
equipment in the

"THE MONARCH" & "THE EMPEROR"

25-9-79



© 2020

Lloyd's Register
Foundation