

4E

3 MAY 1955

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"WYRE WARRIOR"

REPORT Mil.

No. 7889

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

urvey REPAIRS TO ~~ENGINES AND BOILERS~~ DUE TO DAMAGE THROUGH

The Surveyor reports a boiler furnace collapsed and fractured, also signs of the combustion chamber tops being overheated and further states that the machinery is in good condition to remain as classed.

In view of the defect in the boiler this statement is not correct.

Further information states that the vessel has been sold for breaking up.

IT IS SUBMITTED action be deferred pending further information regarding breaking up.

The Surveyor should be informed that in view of severe defect in the main ( and only ) boiler his recommendation is not in order, and should have been " the machinery of this vessel is in my opinion eligible to remain as classed subject to the boiler not being used until repaired".

3.5.55.



© 2021

Lloyd's Register  
Foundation

003858-003866-0031