



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

JW/PK

2, Laidlaw Building, Battery Road,

BY AIRMAIL

(P.O. Box 480), Singapore

9th July, 1951.

Telephone: No. 22861

Telegrams: Surveyor

RECEIVED

16 JUL 1951

reference

lassn.(S)

Dear Sir,

Ans......**"DRESTES"**

We have been advised that this vessel is expected to drydock at this port towards the end of the present month and we shall be grateful if you will send us, by airmail, particulars of the original thicknesses of the shell plating if these are available.

The Owners' Superintendent states that the outstanding requirements for the Assignment of Class which were detailed in your letter, and enclosure, of the 27th February, 1951, will be dealt with whilst the vessel is in drydock.

Yours faithfully,

John Wormald
FOR THE SURVEYORS.

The Secretary,
LONDON.

003875-003883-0037

Lloyd's Register
Foundation

M

CLASSIFICATION

H

REQUESTING EARLY REPLY.

This submitted a copy of the attached thicknesses of Plating be forwarded to the Singapore Savings as requested R.S.P 16.751.



© 2020

Lloyd's Register
Foundation