

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen. London

Telephone: ROYal 3551 (6 Lines)

12th August, 1953.

3) Dear Sir,

Motorship "BRUNA"

When this vessel was classed in May, 1952, a notation of LMC 5,52 was assigned subject to the screwshaft, which was showing signs of pitting, being re-examined before the end of April last.

In reply to enquiry regarding this item, the new Owners state that the vessel was drydocked at Ceuta in February last for the purpose of cleaning the hull, and on that occasion the screwshaft was dealt with. It is concluded, in the absence of any report, that these repairs were not effected under your survey, and I shall therefore be glad if you will ascertain whether a survey was held by Lloyd's Agents' Surveyor.

Yours faithfully,

Assistant Clerk to the  
Classification Committee.

W. T. Cromby, Esq.,  
GIBRALTAR.



© 2020

Lloyd's Register  
Foundation

003884-003894-0192