

LLOYD'S REGISTER OF SHIPPING



Port OF FLEETWOOD. 266

19th March, 1958.

This is to Certify that I have
 Surveyed the Boiler ^{part} and Machinery of the S.T. "MARGARET WICKS",
 366 Tons gross of Fleetwood whilst afloat at Fleetwood on 11/10/57 for
 machinery damage and subsequently on slipway
 and that I have transmitted to the Committee of Lloyd's
 Register of Shipping, London, a Report stating that all
 recommendations made by me in connection therewith have
 been carried out to my satisfaction, and that I have
 Recommended that the record of ~~Main Boiler Survey~~ (New) 1,58.
 be made in the Register Book in the case of this vessel.

G.J. ATKINS.

G. J. Atkins

Engineer Surveyor to Lloyd's Register

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."