

Ship's name *ss. GEMMA*

Port *Singapore*

No. *18241*

31 MAY 1965

Class is subject to *OP & slant tube nuts being* Last survey date *7/5/65*.
specially examined at next D.D.

② *P & S. L.P. cyl. ^{upper} port ribs (Milelock 2/63) being exam. by 4/65 (ms).*

Refr.

SRL. Shw ② *Port. L.P. cyl. rib repair for port & to be deleted.*
Further crack in starb L.P. cyl. upper rib drilled at end
and the surveyor recommends that the Starboard
main engine L.P. cylinder upper ^{Port.} rib (Milelock 2/63 and crack)
be examined by 8/65 (3ms).

(port)

G.S. Advanced.

It is submitted that this
vessel is eligible to remain
as CLASSED,

subject to *both in P & S. slant tube nuts,*
& cracks amended in S. L.P. cyl. upper port rib,
without condition in P. L.P. cyl. upper port rib.

by
28/5/65.

(M)
S.R.L. - Appendix Note
no change.

