

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Dear Sirs,
Telegraphic (Inland: Committee, London, Telex
Address (Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

C.
MK/BN

CLASSING LETTER

TAIPEI

63/076 "TAI SHING". As recommended. It is concluded that the screwshaft has been magnetically crack detected, but your confirmation is desired.

I have to inform you that the machinery class is subject to the Main Engine HP and LP slide valve rods (built up by electric welding 10.61) in way of guides being specially examined before the end of the present month and I shall be glad to learn what arrangements the Owners propose to make to deal with this matter.

I would take this opportunity to point out that the Main Boiler Survey will become due at the end of next month.

Yours faithfully,

The Surveyors,
YOKOHAMA

pro Clerk to the
Classification Committee.



© 2020

Lloyd's Register
Foundation

003958-003963-0224