

0119.0

Destined Young

If Summoned while Building Afloat

5

E. NEW YORK.

TELEPHONES { 220 } WHITEHALL  
{ 221 }  
{ 222 }

# LLOYD'S REGISTER OF SHIPPING,

LLOYD'S REGISTER,

LONDON.

17 BATTERY PLACE.

REC'D - 5 FEB 1923

ANS'D 14/2 NEW YORK January 22nd, 1923.

Dear Sir:-

s.s. "ELLENOR" & "ELIZABETH".

With reference to previous correspondence regarding these vessels which were recently assigned in each case, a classification of 100A1 in the Society's Register Book subject to the chain cable and anchors being verified with certificates and found to be in order, I am now enclosing herewith letters received from the Owners and from the Society's Surveyor at Newport News respectively, from which it will be seen that there is considered to be no possibility of obtaining sufficient identification marks from the equipment to enable the required verification of certificates to be carried out.

It is suggested, as the anchors and chains have been in use for a considerable time and are reported to be in satisfactory condition, and in accordance with the Rule requirements as regards length and size, that these might in all the circumstances be accepted by the Committee for the figure "1", and I shall be glad to receive your instructions in the matter in due course.

I am, Dear Sir,

Yours faithfully,



Secretary to the American Committee.

The Secretary,  
London.

SRD:MD  
Encls.



© 2021

Lloyd's Register  
Foundation

003971-003979-0016

003971-003979-0017

800  
3293  
3293  
3490  
1430  
1644  
1644  
1739  
1855  
1940  
1955  
2025  
2025  
2146  
2146  
2150  
2150  
2150  
2150  
2150  
2163  
2163  
2450

RVICE  
ORTO P  
ANTO D  
EST AF  
EDITEF  
SEA POR

23

18 cr  
136  
84

