

21st December, 1942.

This boiler is one of those originally intended for Rowan's Contract No. 1095, and the invoices for the material were sent with the report on the case:- "EMPIRE LANCER", Glasgow Report No.66336.



© 2021

Lloyd's Register Foundation

603971-603974-0085

Thickness of plates { crown

11/16"

Description of longitudinal joint

path of plain part (top