

LOYD'S REGISTER OF SHIPPING

+LMC
M

Received from Chief Ship Surveyor

17 MAR 1960

"MONOWAI"

REPORT

Auk.

No. 8920

Conditions of Class:

SUBJECT to indented shell plates K.7, 8 & 9, L.5, 6, 7 & 8 and G.20 (p.s. from fwd) being specially examined and dealt with as necessary, to leaky rivets in No.9 O.F.side tank (s.s.) being dealt with also to bottom plating being scaled and specially examined, by the S.S.

ndix. (As before ~~or None~~)

EXTENDED SPECIAL SURVEY (C) case - due date 8,60.

resent Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to contact damage.

ures:

ertificate in order (Yes-~~No=None~~)nding: ~~(If any for S.S.)~~

FOR PORTION OF SURVEY HELD:- See List in Ship Reports' Dept.

Completed by:

on:

SUBJECT as above, and to set in shell plates L.12, M.12 & 13, N.11 & 12 (s.s.) and internals in way being specially examined and dealt with as necessary by 6,60.

As Now. Subject

IN S.R.Z. APPENDIX.

Indents in shell plating (p & s) and keel set up amidships.
(Extended SS).

2.41
10/3/60



© 2021

Lloyd's Register
Foundation

or to Lloyd's Register

A. HUNTINGFORD

003971-003979-0096