

COPY REPORTS

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

16th November 1965

Eng. Dear Sir,

m.t. "JOAN" (716 G. Tons)
Chief Engineer Surveyor's Records

It is observed from Lloyd's List that an explosion occurred in the No.1 cargo tank of the above vessel after tank cleaning at Bayonne N.J. on the 11th instant, and that the vessel will proceed to Staten Island for survey and repairs.

We would be glad to receive, in confidence, any available information as to the cause and circumstances of this explosion and, when replying, the letter should be marked for the attention of the Chief Engineer Surveyor's Records.

Yours faithfully,

pro Secretary.

The Secretary,
NEW YORK.

BAM/ST



© 2021

Lloyd's Register
Foundation

003971-003979-0378