

24 MAR 1968

PT SEE ALSO PREVIOUS ENDORSEMENT.

Ship's name "SAND DIVER" Port SOU No. 29440
Last survey date 8.2.65
Class is subject to

Wasted bottom shell plate in way of F.P. tank suction (p.s) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (~~as before~~ or none)

Nature of present survey (afloat ~~and drydocked~~)

Equipment:- Bower anchor and 2 lengths of chain cable supplied to replace lost equipment and 2 lengths of chain cable supplied to replace defective lengths.

Recommendation

SUBJECT as above.

As Now Subject.

C.S.S. Records Dept.
to note.

JH
24/3/68



© 2021

Lloyd's Register
Foundation