

24 APR 1964

Ship's name ASTON VILLA

Port Grimsby No. 30153

Class is subject to

Last survey date 6.3.64

1. A new screwshaft be fitted on ship's return to home port.

MBS due 4.64


Docking Wear down $1/16"$

TS due 4/63, now held

SRL Item dealt with and to delete from the list
~~item~~ An unused screwshaft fitted, the keyway
complies with C1002. The Owners representation does not
request the screw shaft to be changed or replaced.

It is submitted that this
vessel is eligible for THE
RECORD. TS(EL)N 3/64

Without subject



© 2020

Lloyd's Register
Foundation