

K. OKADA

"LUCAS TRADER"

Extracts of Journal

February 1957

Thur.	7th	Left Hiroshima for Kudamatsu 8:35, Arr. 10:30 "Lucas Trader"	Kasado Dry docking	Hose tested sbatb'd side shell plates which were renewed at this time and now placed in good order. Tested F.P.T. and found tank top plate leaked at port side foundation of chain locker, doubler E. welded. Tested A.P.T. and found fore side B.H.D. holed at centre to repair and retest.
Fri.	8th	"Lucas Trader"	Dry docking	Hose tested port side shell plates which were renewed, except above water line in way of stoke and No.4 Holds and found tight. Hydro. tested valve box for fire pump W.T.P. 20 kg/cm ² and found tight.
Sat.	9th	Left Kasado 9:20 Arr. Kudamatsu 10:30 Left Kudamatsu 11:21 Arr. Hiroshima 13:20.		

The end for s.s. "Lucas Trader"



© 2020

Lloyd's Register
Foundation

004049-004054-0041