

THROUGH ROTTERDAM

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex  
Telex No.: 24305

Telephone: ROYal 9166

6th April, 1960.

Classn (S)  
AH/BS

Dear Sirs,

Motorship "LOUIS LANTZ"

The Society's Surveyors at Emden have reported that this ship was under survey in February when Metalock repairs were carried out to the steering engine starboard cylinder which was cracked.

It was recommended that these repairs should be specially examined by the end of November, 1960, and the Committee have continued the class of the ship subject to this inspection being carried out by that time.

Yours faithfully,

Deputy Clerk to the  
Classification Committee.

c.c. ROTTERDAM

Messrs. N.V. Scheepv. Maats. "Mineral",  
ROTTERDAM.



© 2020

Lloyd's Register  
Foundation

004055-004061-0081