

17 AUG 1921

at to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "HESPERIA".

Report

Npt. 20131  
Liv. No. 82426.  
Npt. 20130.

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/10/21.)

ature of Survey

When due

100 A.1. "Shelter deck with freeboard". ( Subject to the bower anchors  
( being replaced by others of  
( an approved pattern of  
( equal weight and proper test  
( within a reasonable period.

1 Dk.(Steel) & Shelter Dk.(Steel), 2nd.Dk.(Steel) in fore hold.

Cell DB 346', 1140t., FPT 40t., APT 47t.

FK., Collision BH to Shelter Dk., 5 BH to Upper Dk., Cem.

Date of build 1919.

7.21 Liv.

S.S.Npt.No.3-4.21.




1 OCT 1958

See letter  
20.8.21

15. 8. 21.

It is concluded the side stringers in the machinery space are as shewn on the plan of Midship Section, and that the ceiling has been removed as required, but the Newport Surveyors should be requested to state if this is so.

Gr. Npt. 19/8/21



© 2020

Lloyd's Register  
Foundation

004062-004066-0102