

record ❖ L.M.C. 7.24 (in red) in register book it having

s/s "Lethbridge".

Jlpl 16207.

It is submitted the West Hartlepool  
Surveyors be informed that the Rule diameters  
of the shafting given in their report is not  
correct & it is concluded that a clerical error  
has been made.

JWD  
21/7/24

© 2020

Lloyd's Register  
Foundation

004062-004066-0212