

Received from Chief Ship Surveyor

2 OCT 1954

Re

SHIP'S NAME  
JD.

"TOKO MARU"

REPORT

Kob.

No. 2283

Outstanding Conditions of Class: Subject to the spare bower anchor  
(defective) being renewed at the earliest opportunity.

Endorsement of Class (B) (~~As before~~ or None)

Nature of Present Survey: (~~Afloat and~~ in dry dock)

Permanent repairs to damage caused by contact  
a floating object.  
Spare bower anchor as above repaired, tested

Recommendation:

SUBMITTED record of docking 8,54 be  
assigned, as recommended, subject to  
sternframe (E.W. & reinforced 8,54) being  
specially examined at the next drydocking,  
but without other conditions.

8,54 Osa. Subject  
Without.



© 2020

Lloyd's Register  
Foundation

004068-004075-0177