

13 JAN 1964

Ship's name "PAKISTAN PROSPERITY" Port Krh No. 316

Last survey date 24.12.63

GB

Class is subject to For conditions of class see previous endorsement.

S.R.L. Appendix (as before ~~or annex~~)

Nature of present survey (afloat and ~~in~~ drydock) ~~x~~

Equipment - renewal of spare bower anchor shackle as above.

Recommendation

SUBJECT to shell plates A.2, B.1 & C.2 (p.s.a), E.1 & 2, H.5 (p.s.f) B.2, C.2 and G.5 (s.s.a), A.1 (s.s.f) (doubled 10,63) being specially examined and dealt with as necessary at the next drydocking and to a bower anchor and 45 fathoms of chain cable being supplied at the earliest opportunity, but without other condition.

As Now. Subject  
Without.

IN S.R.L. APPENDIX.

Shell plate No. 4 in 1st below sheer  
abreast No. 1 hold (p.s) indented.



© 2020

Lloyd's Register  
Foundation

*R/S*  
*10/1/64*

004076-004083-0232