

Lloyd's Register of Shipping,
36 Furness Withy Building,
Halifax, N.S.

May 13, 1949.

E.R. Macmillan,
Montreal.

M.V. "SEEKONK"

Dear Mr. Macmillan:

We acknowledge your letter of the 26th April last, in connection with further particulars on the survey which was commenced at San Francisco in January 1949.

For your information, the following particulars have been collected, some of which do not agree with the enclosed L.L. 4 C/D form.

Vessel owned by: Messrs. Newfoundland Tankers Limited.

Port of Registry- St. John's, Newfoundland.

Gross tons- 1139.27 Registered tons- 579.49

Deck- 831.94 tons (St. John's Register 18-3-49.

Registered dimensions- length 213.85' breadth 37.15' Depth 14.5'

Ports of Survey.

Commenced at San Francisco, Dec. 1948.

Continued at San Diego, Cal., March 1949.

Completed at Liverpool. N.S., May 12, 1949.


Reference letters V.O.X.K. Official Number 191213.

The questionable items on the enclosed L.L. 4 C/D form have been corrected after alterations at Liverpool and are noted thereon in type.

Regarding the Head Office letter dated 14/3/49 (Reference T26/T22) the enclosed reports will show all items have been attended to, except where otherwise stated.

We would point out that, owing to the loss of the "LKHOUND" this vessel had to be rushed to take her place. You would note that the ELKHOUND blew up and sank at Newcastle, N.B. last week.

Provisional Freeboard and Classification certificates have been issued on L.R. forms and accompany reports (copies were placed on board) also, we return to you all the reports which you were good enough to forward. L.L. 4 C/D form is also enclosed.



© 2020

Lloyd's Register
Foundation

single, triple, screw M. V. TANKER "SEERONK"
f the
--2--

The trunk top is parallel to keel, not to sheer of vessel.

As far as could be seen, this vessel appeared to be in good condition, with the exception of ventilation in engine room. (Trunking system) Prior to leaving Liverpool all fan motors were overhauled and are now in good operating condition. These were not in working order on vessel's arrival.

We hope the foregoing will give you all the information you require for Head Office.

Yours faithfully,

Sgd. Thos. Laurie.



© 2020

Lloyd's Register
Foundation

0056 2/2