


COPY

LLOYD'S REGISTER OF SHIPPING



11,326

Port SAN FRANCISCO

12th December 1959

This is to Certify that I have
 Surveyed the S/S "GUAM PIONEER" (ex Los Aztecas) 2283 tons gross of
 iron hull afloat and in drydock at Alameda, California for repairs
 temporary repairs to damage stated sustained by vessel grounding near
 rracios A. Dios off coast of Honduras at 23.40 hours on the 20th
 r 1959 while on voyage from Puerto Barrios, Guatemala to Kobe, Japan
 nama Canal. Vessel being diverted to San Pedro and San Francisco,
 rnia for repairs.

and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report, stating that all repairs recommended by
 me have been completed to my satisfaction, also that I will
 Recommend that she be retained as now Classed with fresh record
 of DS 12/59 subject to plug rivet in shell plate B 4 being
 renewed at the next drydocking.

(Signed) E. MARLBOROUGH

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
 it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
 held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
 Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
 thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B) 15M 8-59 PRINTED IN U. S. A.

004084-004092-0214

