



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Bank Chambers, 2, Freeman Street, Grimsby

Telephone No. 3156

17th August, 1961.

Enclosure.

Reference

Dear Sir,

.(S)

S/T. "NORTHERN DAWN" - Gms.Rpt.No.28808.

With reference to your Classing Letter dated 16th August, we are pleased to advise that the Screwshaft was examined on the 25th July, 1961, and owing to two visits and journal entries being made for the same day, the later visit for the Screwshaft was overlooked when preparing the report.

We attach a copy of the amended Interim Certificate issued in this case, and should be grateful if you would kindly add the relevant Screwshaft information to our Report No.28808. An account for £5. 0. Od. has been sent to the Owners with the amended Interim Certificate.

Our error in this case is indeed regretted.

We are, Dear Sir,
Yours faithfully,
The Surveyors,

Per:-

The Secretary,
LONDON.

004093-004100-0077

ER

REPORTS

TM

Assign S-6/6
(see ind. in Lms. 28808)

Q 2/8/61

Ref: - 9/1/1961

LONDON
The Secretary



© 2020

Lloyd's Register
Foundation

Bank Chambers, 3, Fiechter Street, Geneva

LOYD'S REGISTER OF SHIPPING

LOYD'S

DATE: 10th December, 1961