

COPY

LLOYD'S REGISTER OF SHIPPING



Port HALIFAX, N. S.,

September 28, 1961

This is to Certify that I have

PART

examined the Machinery of the T.S.S. "LIVERPOOL ROVER", 4454 tons gross register as she lay on the blocks in Halifax Shipyards floating drydock on 25th September 1961 on account of damage to the port propeller shaft, alleged to be caused by propeller striking a submerged object on 22/9/61 during a voyage from Halifax, N.S. to Liverpool, N.S. in loaded condition.

that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by the Committee in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following particulars be made in the Supplement to the Register Book

T.S.S. G.L. P.9/61

that her Machinery Classification Record be continued in the Book.

as previously recorded, to the port main boiler not being used and being further examined and repaired.

now examined:

S. Items only)

L. M. Mathers

(L. M. MATHERS)

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS


ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft Survey—Oil Gland
TS(OG) Tailshaft Survey—Oil Gland

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, and that the Committees of the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, Surveyors, or other Officers or Agents of the Society."

150m,5,60 (MADE AND PRINTED IN ENGLAND)



© 2020

Lloyd's Register
Foundation

004153-004159-0060